National Transportation Sufety Board FACTUAL REPORT AYIATION

NTSB ID: DCA05MA037 Aircraft Registration Number: N500AT

Occurrence Date: 02/16/2005 Most Critical Injury: Fatal

Occurrence Type: Accident Investigated By: NTSB

Location/Time

Nearest City/Place	State	Zip Code	Local Time	Time Zone	
Pueblo	со		0913	MST	
Airport Proximity: Off Airport/Airstrip	Distance Fror	n Landing Facility:	4	Direction Fro	m Airport:

Aircraft Information Summary

Aircraft Manufacturer	Model/Series	Type of Aircraft
Cessna	560	Airplane

Sightseeing Flight:

Air Medical Transport Flight:

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On February 16, 2005, at approximately 0913 mountain standard time (MST), a Cessna Citation 560, registration N500AT, crashed while on an ILS approach to runway 26R at Pueblo Memorial Airport, Pueblo, Colorado (PUB). The two flight crewmembers and six passengers were fatally injured, and the airplane was destroyed by impact and a post-crash fire. The accident site was located in an open field approximately 4 miles east of the runway. The airplane was owned and operated by Circuit City Stores, Inc. of Richmond, VA, utilizing the aircraft management services of Martinair. The flight was being conducted in accordance with 14 CFR Part 91, and instrument meteorological conditions (IMC) prevailed on the approach.

The public docket on this accident contains factual reports and documentation in the following areas: Operations, Weather, Air Traffic Control, Airworthiness, Powerplants, Maintenance Records, Survival Factors, Cockpit Voice Recorder, and Aircraft Performance.

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DCA05MA037

Occurrence Date: 02/16/2005

AVIATION		Occurrence Type: Accident											
Landing Facility/Approach In	formation	•											
Airport Name	Airport Name Airp				irport Elevat	ion	Run	way Used	Runwa	y Lengt	th	Runw	vay Width
Pueblo Memorial Airport KF			KPUB		4726 Ft.	MSL	_ 26R 1049			6			
Runway Surface Type: Asphalt													
Runway Surface Condition:													
Type Instrument Approach: ILS-co	omplete												
VFR Approach/Landing:													
Aircraft Information													
Aircraft Manufacturer			Mode	l/Se	ries						Numbe	er	
Cessna			560							560-0	0146		
Airworthiness Certificate(s): Norm	ıal												
Landing Gear Type: Retractable	- Tricycle												
Homebuilt Aircraft?	Number of Seats:		Certific	Certified Max Gross Wt.					19000 LBS Number			er of Engines: 2	
• • • • • • • • • • • • • • • • • • • •				Engine Manufacturer: Model/Series: JT15D-5A								d Power: 0 LBS	
- Aircraft Inspection Information													
Type of Last Inspection			Date of La	Date of Last Inspection Time Since Last Inspection						Airfran	ne To	tal Time	
Continuous Airworthiness				Hours							3657.5 Hours		
- Emergency Locator Transmitter (ELT) Information												
ELT Installed?	ELT Operate	ed?				EL1	Aided i	n Locating A	ccident S	ite?			
Owner/Operator Information													
Registered Aircraft Owner Street Address													
Circuit City Stores, Inc			City	1 :							Stat	е	Zip Code
				Richmond VA Street Address									
Operator of Aircraft													
Same as Reg'd Aircraft Owner			City	City						Stat	e	Zip Code	
Operator Does Business As: Operator Designator Code:													
- Type of U.S. Certificate(s) Held: I	Vone												
Air Carrier Operating Certificate(s)	:												
Operating Certificate:	Operating Certificate: Operator Certificate:												
Regulation Flight Conducted Under: Part 91: General Aviation													
Type of Flight Operation Conducted	d: Executive/Corp	orate											
		FACT	JAL REPO	ORT	- AVIATI	ON							Page 2

National Transportation Safety Board

FACTUAL REPORT

AVIATION

NTSB ID: DCA05MA037

Occurrence Date: 02/16/2005

AVIATI	Occurrence Type: Accident											
First Pilot Information												
Name					City	State Date of E						Age
On File												53
Sex: M Seat Occupied	: Left	Prin	cipal Profes	sion:				С	ertifica	te Num	ber:	
Certificate(s): Airline Transport; Flight Instructor; Commercial												
Airplane Rating(s): Multi-engine Land; Single-engine Land												
Rotorcraft/Glider/LTA:												
Instrument Rating(s): Airp	lane											
Instructor Rating(s): Airplane Single-engine												
Type Rating/Endorsement for	or Accident/In	cident Aircraf	t?			Cui	rrent Bier	nnial Flight	Revie	w? 11/2	2004	
Medical Cert.: Class 1	Medica	l Cert. Status	: With Wa	ivers/Limita	ations	•		Date of	Last M	edical E	Exam: 02/200	5
	•											
- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Night		Ins:	trument Simulate	d	Rotorcraft	Glider	Lighter Than Air
Total Time	8577	2735										
Pilot In Command(PIC)	4452	1500										
Instructor												
Last 90 Days	113											
Last 30 Days	39											
Last 24 Hours	3											
Seatbelt Used?	Shou	Ider Harness	Used?		Т	oxicolo	ogy Perfo	rmed? Ye	s	S	econd Pilot? \	Yes
Flight Plan/Itinerary												
Type of Flight Plan Filed: IF	R											
Departure Point						State	Airport Identifier Departure Time				Time Zone	
Columbia					N	ИΟ					CST	
Destination						State	Air	port Identi	fier			
PUEBLO							CO PUB					
Type of Clearance: IFR												
Type of Airspace:												
Weather Information												
Source of Briefing:	nercial Weat	her Service										
Method of Briefing:												
				L REPORT								Page 3

National Transportation Safety Board FACTUAL REPORT AVIATION

NTSB ID: DCA05MA037

Occurrence Date: 02/16/2005

	ETYBOR		Ос	Occurrence Type: Accident									
Weather Information													
WOF ID	Observation Time	Time Zone	WOF	Elevati	on	WOF Distance From Accide			dent Site Direction From Accident S			Site	
KPUB	0853	MST	4	725 Ft.	MSL				3 NM			270 De	eg. Mag.
Sky/Lowes	t Cloud Condition:						Ft. A	GL	Condition o	f Ligh	nt: Day		
Lowest Ce	iling: Broken		(900 Ft.	AGL	Visib	oility:	8	SM	Altii	meter:	30.16	"Hg
Temperatu	ıre: -3 °C	Dew Point:		-5 °C	Wind	Direction	: 60			Dei	nsity Altitude:		Ft.
Wind Spee	ed:	Gusts:			Weath	ner Cond	tions at Acc	ident S	ite: Instrume	ent C	Conditions		
Visibility (R	RVR): Ft.	Visibility	y (RVV)		SM	Intensit	ty of Precipit	tation:					
Restriction	s to Visibility:												
Type of Pre	ecipitation:												
Accident	Information												
Aircraft Dar	mage: Destroyed		Airc	Aircraft Fire: Ground					Aircraft Explosion None				
Classificati	on:												
- Injury Su	mmary Matrix	Fatal	Serious	Mino	or	None	TOTAL						
First Pi	lot	1					1						
Second	d Pilot	1					1						
Studen	t Pilot							7					
Flight I	nstructor							1					
Check	Pilot							1					
Flight E	ngineer							1					
Cabin A	Attendants							1					
Other C	Crew							1					
Passen	igers	6					6	5					
- TOTAL A	ABOARD -	8					8	3					
Other G	Ground							1					
- GRAND	TOTAL -	8					8	3					

National Transportation Safety Board
0 7
FACTUAL REPORT

NTSB ID: DCA05MA037

National Transportation Safety Board	WIGHT. DOAGSWAGG	-
FACTUAL REPORT	Occurrence Date: 02/16/2005	
AVIATION	Occurrence Type: Accident	
Administrative Information		
Investigator-In-Charge (IIC)		
Frank Hilldrup		
Additional Persons Participating in This Accident/Inci-	dent Investigation:	